

## EclairXL - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
87	Feature	New	Normal	SI5351 interesting library		11/27/2021 09:15 AM
86	Feature	New	High	Keyboard expansion board support on the mini		01/14/2021 10:39 AM
85	Feature	In Progress	Normal	720p support/1080i support		01/14/2021 10:29 PM
84	Feature	New	Normal	Add SID		01/14/2021 10:35 AM
82	Feature	New	Normal	Setting for mono pokey		01/14/2021 10:36 AM
79	Feature	New	Normal	SDHC and SDXC support		05/28/2019 09:31 PM
77	Feature	New	Normal	Add yPbPr support		02/20/2019 10:43 PM
76	Feature	Resolved	High	Merge down to trunk		09/23/2021 08:45 PM
71	Feature	New	High	Add support for user firmware updates		08/01/2018 10:04 PM
65	Feature	New	Normal	Implement ATA to SPI bridge		06/11/2018 09:09 PM
55	Feature	New	Normal	Replace main CPU		09/26/2017 09:35 PM
51	Feature	New	Normal	Debug port		11/09/2019 09:55 AM
40	Feature	New	Normal	Add support for Interlace mode (in scaler)		06/04/2017 02:13 PM
32	Feature	New	Normal	option to connect the original ATARI XL keyboard to ExclairXL	foft	11/09/2019 09:58 AM
15	Feature	New	Normal	Implement programmable PLL		02/06/2018 09:15 PM
13	Feature	New	Normal	32x speed cpu without wait states	foft	05/31/2017 06:57 PM
11	Feature	New	Normal	Non-uk keyboard support (custom keyboard mapping)		06/23/2017 07:27 AM
7	Feature	New	Normal	Implement I2C vga/hdmi support		02/07/2018 08:51 PM
3	Feature	New	Normal	High resolution antic support		01/14/2021 10:41 AM
69	Bug	New	Normal	Some TVs confused by hdmi audio		11/09/2019 10:00 AM
67	Bug	Resolved	Normal	Pokey two tone timing problem		09/23/2021 08:44 PM
63	Bug	New	Normal	Svideo issues in v20 on board v1		02/24/2018 08:56 PM
50	Bug	New	Normal	CORE13 - Option on initial powerup does not disable BASIC		06/13/2017 08:24 PM
42	Bug	New	Normal	Core 8 - Mic level is low	sadosp	09/23/2021 08:48 PM
41	Bug	New	Normal	Core 8 - the background music in Gene & LMS demos are not the same as on a real ATARI	foft	06/07/2017 10:46 PM
35	Bug	New	Normal	When connecting ST Mouse to any JOY PORT on the expansion port, navigation on the EclairXL Settings menu not possible (Core8)	foft	06/03/2017 12:29 PM
25	Bug	New	Normal	F10 Hard Reset Ignore inserted cartridge (Core v7)		08/01/2018 10:01 PM
22	Bug	New	Low	Action and Bounty Bob Cartridges cannot be loaded		05/31/2017 06:49 PM