

EclaireXL - Bug #5

SIDE2 does not work

04/04/2017 09:05 PM - admin

Status:	Closed	Start date:	04/04/2017
Priority:	Normal	Due date:	
Assignee:		% Done:	0%
Category:		Estimated time:	0:00 hour
Target version:			
Description			
SIDE1 works fine, but SIDE2 does not work. I contacted Sebastian and he kindly send me some details. Need to look into this. Suspect its down to dynamic RD4/RD5.			
Related issues:			
Related to Feature #2: PBI support		Closed	04/04/2017

History

#1 - 05/31/2017 07:03 PM - foft

- Related to Feature #2: PBI support added

#2 - 06/03/2017 09:04 AM - ndary

I Confirm that SIDE 2 cart work on core8, should we close this bug?

Nir

#3 - 06/03/2017 12:31 PM - foft

In v8, uh oh! I don't think I changed anything before v8 that would fix this... I will have to get RoyE to double check with the v9 core on the v1 prototype.

#4 - 06/03/2017 08:41 PM - RoyE

foft wrote:

In v8, uh oh! I don't think I changed anything before v8 that would fix this... I will have to get RoyE to double check with the v9 core on the v1 prototype.

I can confirm that Side 2 is now booting with SDX and the Sideloader rom..
I just now flashed the v9 core for Version 1 prototype..
RoyE.

#5 - 06/03/2017 08:44 PM - foft

- Status changed from New to Closed

Great, thanks Roy. Will close this for now, please reopen if it breaks again!