

EclairerXL - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
66	Bug	Closed	Urgent	Odd flash behaviour on new boards	foft	07/22/2018 09:19 PM
81	Feature	Closed	High	Breakpoint support for turbo freezer	foft	09/11/2019 10:20 PM
14	Feature	Closed	High	Svideo core for first prototype	foft	02/08/2018 07:55 PM
2	Feature	Closed	High	PBI support	foft	01/09/2018 08:54 PM
83	Bug	Closed	Normal	Many USB hubs do not work	foft	11/09/2019 09:44 AM
62	Feature	Closed	Normal	Store settings in spi flash	foft	02/17/2018 05:19 PM
47	Bug	Closed	Normal	CORE 13 - Paddle, Touchtablet issues	foft	02/08/2018 09:09 PM
44	Bug	Closed	Normal	CORE 11 - Bug in PBI - EclairerXL will not boot with IDE2+ Is connected and when Turbo Freezer connected goes directly to Cart EMU not main screen	foft	06/11/2017 03:07 PM
43	Bug	Closed	Normal	Core 10 - IDE2+ Menu does not show when powering the computer with START key pressed	foft	01/09/2018 08:45 PM
36	Bug	Rejected	Normal	Joystick is always emulated through the USB keyboard arrow keys	foft	06/03/2017 12:23 PM
34	Bug	Closed	Normal	Problem booting with Core 9	foft	06/11/2017 03:09 PM
28	Feature	Closed	Normal	XEX boot loader replacement	foft	06/06/2017 08:57 AM
21	Feature	Closed	Normal	Mirax Force game crash	foft	06/03/2017 12:23 PM
19	Bug	Closed	Normal	PAL VGA Synch issues (screen is not centered)	foft	05/30/2017 06:46 PM
8	Feature	Closed	Normal	Implement 4 channel ADC	foft	05/30/2017 07:00 PM