

EclairXL - Issues

#	Tracker	Status	Priority	Subject	Assignee	Updated
22	Bug	New	Low	Action and Bounty Bob Cartridges cannot be loaded		05/31/2017 06:49 PM
50	Bug	New	Normal	CORE13 - Option on initial powerup does not disable BASIC		06/13/2017 08:24 PM
25	Bug	New	Normal	F10 Hard Reset Ignore inserted cartridge (Core v7)		08/01/2018 10:01 PM
67	Bug	Resolved	Normal	Pokey two tone timing problem		09/23/2021 08:44 PM
69	Bug	New	Normal	Some TVs confused by hdmi audio		11/09/2019 10:00 AM
63	Bug	New	Normal	Svideo issues in v20 on board v1		02/24/2018 08:56 PM
42	Bug	New	Normal	Core 8 - Mic level is low	sadosp	09/23/2021 08:48 PM
41	Bug	New	Normal	Core 8 - the background music in Gene & LMS demos are not the same as on a real ATARI	foft	06/07/2017 10:46 PM
35	Bug	New	Normal	When connecting ST Mouse to any JOY PORT on the expansion port, navigation on the EclairXL Settings menu not possible (Core8)	foft	06/03/2017 12:29 PM