

EclaireXL - Issues

| # | Tracker | Status | Priority | Subject | Assignee | Updated |
|----|---------|----------|----------|---|----------|---------------------|
| 69 | Bug | New | Normal | Some TVs confused by hdmi audio | | 11/09/2019 10:00 AM |
| 67 | Bug | Resolved | Normal | Pokey two tone timing problem | | 09/23/2021 08:44 PM |
| 63 | Bug | New | Normal | Svideo issues in v20 on board v1 | | 02/24/2018 08:56 PM |
| 50 | Bug | New | Normal | CORE13 - Option on initial powerup does not disable BASIC | | 06/13/2017 08:24 PM |
| 42 | Bug | New | Normal | Core 8 - Mic level is low | sadosp | 09/23/2021 08:48 PM |
| 41 | Bug | New | Normal | Core 8 - the background music in Gene & LMS demos are not the same as on a real ATARI | foft | 06/07/2017 10:46 PM |
| 35 | Bug | New | Normal | When connecting ST Mouse to any JOY PORT on the expansion port, navigation on the EclairXL Settings menu not possible (Core8) | foft | 06/03/2017 12:29 PM |
| 25 | Bug | New | Normal | F10 Hard Reset Ignore inserted cartridge (Core v7) | | 08/01/2018 10:01 PM |
| 22 | Bug | New | Low | Action and Bounty Bob Cartridges cannot be loaded | | 05/31/2017 06:49 PM |