## EclaireXL - Issues

| #  | Tracker | Status   | Priority | Subject   | Assignee | Updated             |
|----|---------|----------|----------|---|----------|---------------------|
| 69 | Bug     | New      | Normal   | Some TVs confused by hdmi audio   |          | 11/09/2019 10:00 AM |
| 63 | Bug     | New      | Normal   | Svideo issues in v20 on board v1  |          | 02/24/2018 08:56 PM |
| 50 | Bug     | New      | Normal   | CORE13 - Option on initial powerup does not disable BASIC   |          | 06/13/2017 08:24 PM |
| 42 | Bug     | New      | Normal   | Core 8 - Mic level is low   | sadosp   | 09/23/2021 08:48 PM |
| 41 | Bug     | New      | Normal   | Core 8 - the backgound music in Gene & LMS demos are not the same as on a real ATARI  | foft     | 06/07/2017 10:46 PM |
| 35 | Bug     | New      | Normal   | When connecting ST Mouse to any JOY PORT on the expantion port, navigation on the EclairXL Settings menu not possible (Core8) | foft     | 06/03/2017 12:29 PM |
| 25 | Bug     | New      | Normal   | F10 Hard Reset Ignore inserted cartridge (Core v7)  |          | 08/01/2018 10:01 PM |
| 67 | Bug     | Resolved | Normal   | Pokey two tone timing problem   |          | 09/23/2021 08:44 PM |
| 22 | Bug     | New      | Low      | Action and Bounty Bob Cartridges cannot be loaded   |          | 05/31/2017 06:49 PM |